



NEW ICS & EPPIII In Cab control Equipment



The existing ICS that introduced 2004, is replaced by the new model which features a larger screen and fully proportional control buttons on top of the joystick.

The replacement ICS hand set will have an improved blue push button keypad. All other top face details remain the same including the three axis joystick.

Other changes to the ICS are to the CAN loom connections on the underside from round to square. The current ICS can loom will be replaced. The replacement can loom is characterised by the reinforced wire together with the square, sealed plugs and socket.



The familiar shape and appearance of the EPPII, introduced in 1977 has been replaced by the totally redesigned



The new face of the EPPIII hand set is very similar to the ICS but without the central screen. Other details are the new three axis joystick with single top, none latching, button. The keypad buttons are activated as the ICS.

Features:- Diagnostics. When joystick is in neutral all LED lights are off. If green LED is on then there will be a joystick problem. If all green LEDs flash then there is a communication problem between the Handset and the ECU. The current ICS loom is replaced. The replacement loom is characterised by the reinforced wire together with the square, sealed plugs and socket

Contact Chris Tucker for photos and general information. ctucker@bomford-turner.com Tel: 01789 773383